

**We** MERSEN FRANCE SB  
15, Rue Jacques de Vaucanson 69720 SAINT BONNET DE MURE FRANCE

**Certify that products with the registered trade mark Mersen**

**Product type** High-Speed and Semiconductor protection fuses  
Square Body High-Speed Fuse-Links AC Protection

**Model Series Line** Protistor® size 73 aR, 600 to 1250VAC (IEC) / 1300VAC (UL)

**References** please refer to page 2 for catalog number

**comply with the EU RoHS (Restriction of Hazardous Substances) Directives:**

**RoHS directive N° 2011/65/UE**

**RoHS directive N° 2015/863**

[https://ec.europa.eu/environment/waste/rohs\\_eee/index\\_en.htm](https://ec.europa.eu/environment/waste/rohs_eee/index_en.htm)

and declare that the materials and the processes used to manufacture the above-mentioned parts do not contain any of the restricted substances beyond their specified limit at homogeneous material level as mentioned in the table:

Sl. No.	RoHS Restricted Substances	Max. Concentration
1.	Cadmium	0.01%
2.	Mercury	0.1%
3.	Lead	0.1%
4.	Chromium VI	0.1%
5.	Polybrominated biphenyls (PBB)	0.1%
6.	Polybrominated diphenyl ethers (PBDE)	0.1%
7.	Bis(2-ethylhexyl) phthalate (DEHP)	0.1%
8.	Butyl benzyl phthalate (BBP)	0.1%
9.	Dibutyl phthalate (DBP)	0.1%
10.	Di-isobutyl phthalate (DIBP)	0.1%

**Any exemptions are listed below and exemption validity dates are monitored by Mersen.**

The information provided is based upon data obtained from ongoing due diligence concerning goods and materials provided by our suppliers. Mersen reserves the right to update and modify this communication, as it believes necessary or appropriate.

**Date / Location :** 16.04.2026 / Saint Bonnet de Mure

**Name :** Pierre LAVAUD

**Position / Signature :**  
Head of R&D department  
For the president and by delegation *Pierre Lavaud*

## Catalog number list

Catalog number	Item number	ROHS exemption
PC73UD13C315D1A	A300564	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C350D1A	B300565	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C400D1A	C300566	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C450D1A	D300567	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C500D1A	E300568	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C550D1A	F300569	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C630D1A	G300570	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD11C800D1A	J300572	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD12C700D1A	H300571	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD90V10CD1A	L300574	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD90V11CD1A	M300575	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD10C900D1A	K300573	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C315EF	V300628	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact

		fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C350EF	W300629	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C400EF	X300630	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C450EF	Y300631	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C500EF	Z300632	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C550EF	A300633	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C630EF	B300634	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD11C800EF	D300636	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD12C700EF	C300635	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD90V10CEF	F300638	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD90V11CEF	G300639	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD10C900EF	E300637	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A090UD73LI1400	K301194	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73LI315	B300680	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)

A130UD73LI350	C300681	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73LI400	D300682	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73LI450	E300683	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73LI500	F300684	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73LI550	G300685	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73LI630	H300686	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A100UD73LI1000	M300690	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A120UD73LI800	K300688	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73LI700	J300687	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A110UD73LI900	L300689	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A100UD73LI1100	N300691	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A100UD73LI1250	J301193	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C450PA	X302976	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C500PA	S302719	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact

		fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C550PA	Y302977	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A090UD73PA1400	G302709	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD11C800PA	Z301966	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD85V14CPA	G302686	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD90V10CPA	R302718	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD90V11CPA	Q302717	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD10C900PA	F302685	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD12C900TF	T300512	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C315TF	J300503	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C350TF	K300504	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C400TF	L300505	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C450TF	M300506	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C500TF	N300507	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)

PC73UD13C550TF	P300508	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C630TF	Q300509	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C700TF	R300510	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD13C800TF	S300511	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD10C1000TF	V300513	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD69V16CTF	B301301	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD85V14CTF	S300718	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD90V13CTF	T300696	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD95V11CTF	W300514	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
PC73UD60V18CTF	C301302	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI315	Z301046	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI350	A301047	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI400	B301048	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI450	C301049	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact

		fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI550	E301051	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI630	F301052	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI700	G301053	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A090UD73TTI1400	N301059	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A100UD73TTI1100	L301057	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A100UD73TTI1250	M301058	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI800	H301054	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A130UD73TTI900	T1013903	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A110UD73TTI1000	K301056	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A070UD73TTI1600	Q300877	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)
A065UD73TTI1800	R300878	6(b) - for aluminum alloys (signalization pin) 6(c) - for copper alloys (Brass for Flush end contact fuse only) 7(a) - for lead alloys (High temperature solder)