

"CP" CABLE PROTECTOR AMP-TRAP FUSE
 STANDARD DUTY
 FOR COPPER & ALUMINUM CABLE
 600 VOLT
#2, 1/0, 2/0, 4/0, & 250-1000 MCM
MELTING TIME CURRENT CURVE
 FERRAZ SHAWMUT
 NEWBURYPORT, MA 01950

08011

CURRENT IN AMPERES

